

# Hot water tank condition assessment

## USING MORDEN SCANNING EQUIPMENT


Páll Baldvin Sveinsson  
Operation Manager District Heating

2019

# Overview of the Distribution System

- Power: About 900 MW heat power
- Pipe length: 5.600 km
- Pipe max diameter: 1,0m
- Number of tanks: 30
- Total tank size: 110.000 m<sup>3</sup>
- Age of tanks ranging from 5 to 40 years
- Tank size ranges from 10m<sup>3</sup> to 10.000 m<sup>3</sup>

Main pipes 350 mm and larger



# Grafarholt's tanks Reykjavík

51.000 m<sup>3</sup>, water temp. 80°- 90°C



# Challenges - Operation of Tanks

1. Corrosion in steel
  - Corrosion from inside
    - Often above water level
  - Corrosion from outside
    - Water gets through the tank's weathercoat
2. Corrosion protection inside the tanks
  - New methods of corrosion protection that last longer are being explored
3. Good methods to assess the condition of the tank

# Current State Assessment

The condition of the tanks has been assessed

- Inspection every 7 years
- Visual inspection
- Spot metering
- Repair history
- Security perspective



# Condition Assessment – New Methods

In addition to traditional methods

- Scanning
  - Evaluate the steel thickness in the tankwalls and -floor
- Thermal camera using drones
  - Evaluate the surface of the tank
  - Evaluate the insulation of the tank
  - Evaluate the weathercoat



# Tank Scanning

Full scale survey of one district heating tank performed in 2017

- Experts in tank scanning were contracted
- Bottom and walls scanned
- Roof is visually inspected



Construction year: 1987  
Capacity: 8.500 m<sup>3</sup>

# Tank Scanning



- Preparation
  - Empty tank, sandblasting and cleaning
- Scanning
  - The condition assessment took three days + reporting work
- Report
  - Turns out that the tank is in pretty good shape
- Several places mapped where corrosion has started
  - Spot repairs performed



# Tank Scanning - Results

Condition of the tank's bottom

- Damaged in two places where the metal loss is 40% or more



## List of Features

Metal loss 40 % - 100 % ; Size 0.0 mm - 1000.0 mm



All Plates ; All Types ; All Methods (the accuracy of feature pos. is +/- 50 mm)

No.	Plate No.	X Pos. [mm]	Y Pos. [mm]	X Size [mm]	Y Size [mm]	Depth [%]	Type	Method	Location	Classification
1	12	1850	4777	8	11	40	Metal Loss	TBit	SK	Inspection Side
2	55	1387	5083	16	20	65	Metal Loss	TBit	AN / CA	Inspection Side

# Tank Scanning - Results

Condition of the tank's walls

- Corrosion found in two places, metal loss more than 20%



# Tank Scanning – In Action



# Tank Condition Assessment by Thermal Camera


- Can be viewed from outside with tank in operation
- Good analysis of poor insulation
- Benefits
  - Quick analysis
  - No need for tank entry
  - No need to open the weathercoat



# Tank Condition Assessment by Thermal Camera

Use of drones for thermal imaging

- Tanks found in good condition





Thank you

